

SCA50

May 12, 2024 Service

Spray cleaned all pots and selector switch. Made pots feel better, removed the funniness in the selector switch.

Replaced 4 aluminum electrolytic caps on the power amp boards (2 boards, 8 caps in total). C103, C105, C106, C10. Restored flat square wave response.

Reset offset voltage to within about 10 mV of 0.

Set up bias to nominal 45 mA.

Playing CD thru it, sounds clean.

Still needs: working pilot light.





