

Stereo 120 Tag 13

Much more conventional...


A bit of auxiliary heatsinks were added, but otherwise the unit is fairly stock. We have disconnected the transformer output because in its current form, the unit typically blows a fuse if the transformer output is connected to the power supply. Disconnected Transformer output voltage measures good. That's really all you need to know to apply the Upgrade Kit to this unit.






Needs new feet.





Bottom only has two screws.



I put white paper in the bottom of the cover. This clearly shows where this cover has been chopped to allow the auxiliary heatsinks to pass.